

1/19




FIG. 1A




FIG. 1B

CPM Incorporated




FIG. 1C

O.D. 450-570




FIG. 1D

3/19




FIG.2A




FIG.2B

5/19




FIG.2C

6/19




FIG.2D




FIG. 3A





FIG. 3B



9/19

205220 "E484800T






FIG. 5

11/19




FIG. 6




FIG. 7




FIG.8





FIG. 9






FIG.11






FIG. 12A




FIG. 12B




FIG. 12C




FIG. 12D




FIG. 12E